


Pin Layout of Motorized Lab Jack



Limit Switch 1 is at the end of the stepper motor. It's the home (zero) position.

Limit Switch 2 is at the opposite end of the stepper motor.

The lowest position of the top plate is set as the home (zero) position. If you need to set the highest position of the top plate as the home (zero) position, please exchange the wiring of pin 2 and pin 3, pin 6 and pin 7.